### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

## WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-002733 Address: 333 Burma Road **Date Inspected:** 29-May-2008

City: Oakland, CA 94607

**OSM Arrival Time:** 630 **Project Name:** SAS Superstructure **OSM Departure Time:** 1530 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name:** Sun Wei **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:** 

**Bridge No:** 34-0006 **Component:** OBG

### **Summary of Items Observed:**

Caltrans Quality Assurance Inspector (QAI) Bruce Berger arrived on site at the Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island, in Shanghai, China to periodically monitor welding and Quality Control (QC) functions. While on site the QAI observed and/or discovered the following.


The Caltrans QAI observed welding utilizing the dual process WPS-B-T-2342-U1 (U-rib)-3 welding procedure specification (WPS) for closed rib welding of the Production Monitoring Test (PMT) #1 for Production Panel DP563-001 and DP588-001 on closed U-rib Partial Joint Penetration (PJP) welds in Bay #1. ZPMC welding personnel performed Gantry Machine, Gas Metal Arc Welding (GMAW) for the root pass and immediately performed Gantry Machine, Submerged Arc Welding (SAW) for the cover/final pass on PMT #1, using gantry machine #2. Upon completion of the SAW pass on U-rib PJP welds on PMT #1 Visual Testing (VT) was performed on weld #1 through #6 by QC and accepted then VT was verified by the Caltrans QAI. Ultrasonic Testing (UT) was then performed by ZPMC inspector and PMT #1 was determined to be acceptable. Macro etch samples were selected by the Caltrans QAI on PMT #1.

The Caltrans QAI observed ZPMC welders welding the GMAW roots on the following welds. For Deck Panel DP588-001 welder Xiang Jie, WID 059378 on 001, Xiang Huan Feng, WID 059416 on 002, Chen Jie, WID 059468 on 005 and Zhang Shuo Hui, WID 059403 on 006. On Deck Panel DP653-001 welder Xiang Jie, WID 059378 on 001, Xiang Huan Feng, WID 059416 on 002, Chen Jie, WID 059468 on 005, Zhang Shuo Hui, WID 059403 on 006., Jiang Ting Guang, WID 062265 on 009 and Gao Xin Dong, WID 059361 on 010. Essential welding variables recorded below.

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

The Caltrans QAI performed magnetic particle testing (MT) on fillet weld joints DP557-001-056, 057 & 096 between the closed u-rib and diaphragm. All welds appeared to be in compliance with the special provisions and code. See Magnetic Particle Testing Report TL-6028 dated May 29, 2008 for results.





| Item | Weld Identification | Applicable WPS  | CWI Name | Amperage | Voltage | TravelSpeed | Preheat Temp | Remarks    |
|------|---------------------|-----------------|----------|----------|---------|-------------|--------------|------------|
| 1    | DP588-001-001       | WPS-B-T-2342-U1 | Chen Xi  | 368      | 30.2    | 535mm/min   | 47C          | WID 039378 |
| 2    | DP588-001-002       | WPS-B_T-2342-U1 | Chen Xi  | 371      | 30.0    | 535mm/min   | 47C          | WID 059416 |
| 3    | DP588-001-005       | WPS-B-T-2342-U1 | Cheng Xi | 370      | 30.0    | 535mm/min   | 47C          | WID 059468 |
| 4    | DP588-001-006       | WPS-B-T-2342-U1 | Chen Xi  | 370      | 30.0    | 535mm/min   | 47C          | WID 059403 |
| 5    | DP653-001-001       | WPS-B-T-2342-U1 | Chen Xi  | 356      | 30.9    | 530mm/min   | 24C          | WID 059378 |
| 6    | DP653-001-002       | WPS-B-T-2342-U1 | Chen Xi  | 364      | 30.0    | 530mm/min   | 24C          | WID 059416 |
| 7    | DP653-001-005       | WPS-B-T-2342-U1 | Chen Xi  | 368      | 30.4    | 530mm/min   | 24C          | WID 059468 |
| 8    | DP653-001-006       | WPS-B-T-2342-U1 | Chen Xi  | 388      | 30.3    | 530mm/min   | 24C          | WID 059403 |
| 9    | DP653-001-009       | WPS-B-T-2342-U1 | Chen Xi  | 383      | 30.2    | 530mm/min   | 24C          | WID 062265 |
| 10   | DP653-001-010       | WPS-B-T-2342-U1 | Chen Xi  | 365      | 30.1    | 530mm/min   | 24C          | WID 059361 |

## **Summary of Conversations:**

No conversations held today.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Patrick Lowry, 858 344-2712, who represents the Office of Structural Materials for your project.

| Inspected By: | Berger,Bruce | Quality Assurance Inspector |  |  |
|---------------|--------------|-----------------------------|--|--|
| Reviewed By:  | Cochran,Jim  | QA Reviewer                 |  |  |